# FOR LEASE | INDUSTRIAL 2250 FREMONT STREET PORT COQUITLAM, BC









- ▶ 8,716 SF High Quality Warehouse/Office
- ► Three Grade Loading Doors
- **▶** Corner Premises







## Available Space\*

UNITS 170, 180, 190

Main floor warehouse6,765 SFSecond floor mezzanine1,275 SFSecond floor finished office676 SFTotal8,716 SF

\*Approximate

#### Zoning

M3 (Industrial)

#### **Asking Lease Rate**

\$17.95 PSF

### **Taxes & Operating Costs**

\$9.84 PSF (2023 estimate)

#### **Availability**


Immediate


#### Location

The development is located just east of the Pitt River Bridge in the Dominion Triangle Area. The project is south of Dominion Avenue, just west of Fremont Connector. The property offers quick and easy access to Lougheed Highway, the Mary Hill Bypass and the Golden Ears Bridge. The area has developed into a vibrant mix of retail, light industrial, and residential uses. Businesses in the area include Walmart, Home Depot, Canadian Tire, Shoppers Drug Mart, Mark's Work Warehouse, Starbucks, CIBC, RBC, Costco and Mcdonald's.

#### **Features**


- Extensive glazing
- ▶ 25′ clear ceilings
- ► ESFR rated sprinkler system
- ► LED lighting
- ► Three (3) grade level loading doors
- ► Insulated wall panels
- ► Radiant tube heating
- ▶ 3-phase electrical service
- ► Handicap accessible bathroom
- ► Two (2) washrooms
- ► Corner premises








#### MAIN FLOOR PLAN



#### **SECOND FLOOR PLAN**







#### **Tony Capolongo**

D 604.630.3378 C 604.290.5318 tony.capolongo@lee-associates.com

#### Ryan Barichello

D 604.630.3371 C 604.889.4146 ryan.barichello@lee-associates.com

© 2023 Lee & Associates Commercial Real Estate (BC) Ltd. ("Lee & Associates Vancouver"). All Rights Reserved. 1117. E. & O.E.: Although the information contained within is from sources believed to be reliable, no warranty or representation is made by Lee & Associates Vancouver as to its accuracy being subject to errors, omissions, conditions, prior lease, withdrawal or other changes without notice and same should not be relied upon without independent verification.





